

## CORNER RECORD Document Number \_\_\_\_\_ BURBANK County of Los Angeles, California CENTERLINE TIES: CHANDLER BOULEVARD & BEACHWOOD DRIVE **Brief Legal Description CORNER TYPE** COORDINATES (Optional) Govt. Corner Control \_ NAD27 □ NAD83 Zone . Meander Property NAD83 Epoch \_ Rancho Elev.\_ Other X Vert. Datum: NGVD29 □ NAVD88 11-01-00 Date of Survey Meas. Units: Metric Imperial Corner -Left as found Found & tagged Established Reestablished Rebuilt Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: TIED OUT AS FOUND A description of the physical condition of the monument as found and as set or reset: SEE PLAT SURVEYOR'S STATEMENT DAVID L. This Corner Record was prepared by me or under my direction in conformance LINDELL EXP. 6-30-04 with the Land Surveyors' Act on \_\_\_\_\_NOVEMBER 21, 2000 Lindell P.L.S. or R.C.E. No. LS 4016 (EXPIRES 6-30-04)

**COUNTY SURVEYOR'S STATEMENT** 

This Corner Record was received \_\_\_\_\_

and examined and filed \_\_\_\_\_

Signed \_\_\_\_\_\_ P.L.S. or R.C.E. No.\_\_\_\_

Title:

County Surveyor's Comment

82-0029 DPW Rev. 11/00 Borpels-1297